





FRONT


CARPENTER'S MARKS ON JOISTS


XIII b 


XII b 


XI b 


X b 


X 


III b 


III 


II b 


II 


A 


III b 


III 


I b 


NOMARKS 


 1/2 XII


 XI


 X


 XIII


 III X


 NOMARKS


 NOMARKS


 X IIII


 NOMARKS

 X II


 NOMARKS


 NOMARKS


 IX

 II


NOMARKS


 NOMARKS


 NOMARKS


 VI


NOMARKS


 NOMARKS


 NOMARKS


 III

 IIII

 V

 IV

 IIII

 III

NOMARKS