


Detail of window mullion



Alison Welfare

August 1980

Carpenters assembly marks in window mullions
Truss A Ground floor

